


VAKUUMPUMPE VP6 F. DIA.-BOHRSYSTEME

**4932352094 - VACUUM EQUIPMENT VP6 230V P1M -
4000411861**



| Position | Quantity | Description | Part number | EAN |
|----------|----------|----------------------|-------------------------------|-----|
| 0010 1 | 1 | ABDECKUNG | Item discontinued(4931416590) | |
| 0020 2 | 1 | ABDECKUNG | Item discontinued(4931416591) | |
| 0030 3 | 1 | ABDECKUNG | Item discontinued(4931416592) | |
| 0040 4 | 1 | BEHAELTER | Item discontinued(4931416593) | |
| 0050 5 | 1 | PLATTE | Item discontinued(4931416594) | |
| 0060 6 | 1 | HANDGRIFF | Item discontinued(4931416595) | |
| 0070 7 | 1 | FUSS | Item discontinued(4931416596) | |
| 0080 8 | 1 | PUMPE | Item discontinued(4931416597) | |
| 0090 9 | 1 | Druckanzeiger | Item discontinued(4931416598) | |
| 0100 10 | 1 | VERSCHLUSS | Item discontinued(4931416599) | |
| 0110 11 | 1 | FILTER | Item discontinued(4931416600) | |
| 0120 12 | 1 | SCHNELLKUPPLUNG | Item discontinued(4931416601) | |
| 0130 13 | 1 | ANSCHLUSSLEITUNG | Item discontinued(4931416602) | |
| 0140 14 | 1 | SCHALTER | Item discontinued(4931416603) | |
| 0150 15 | 1 | SICHERUNG | Item discontinued(4931416604) | |
| 0160 16 | 1 | SCHLAUCH | Item discontinued(4931416605) | |
| 0170 17 | 1 | FILTER | Item discontinued(4931416606) | |
| 0180 18 | 1 | ANKER F.ELEKTROMOTOR | Item discontinued(4931416607) | |
| 0190 19 | 1 | FILTER | Item discontinued(4931416609) | |
| 1200 20 | 1 | REPARATURSATZ | Item discontinued(4931416608) | |